

# Oil Field Environmental Incident Summary

**Incident:** 20140424154036      **Date/Time of Notice:** 04/24/2014 15:40

**Responsible Party:** Trade Star, LLC

**Well Operator:** TRIANGLE USA PETROLEUM CORPORATION

**Well Name:** SHOCK CTB

**Field Name:** ELK

**Well File #:**

**Date Incident:** 4/23/2014      **Time Incident:** 04:00      **Facility ID Number:** 226723-01

**County:** MCKENZIE      **Twp:** 152      **Rng:** 102      **Sec:** 36      **Qtr:** SE SW

**Location Description:**

**Submitted By:** Allen Harper

**Received By:**

**Contact Person:** Allen Harper  
1200 17TH ST., SUITE 2600  
DENVER, CO 80202-5826

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** Yes

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	2	Barrels		

Brine

Other

**Description of Other Released Contaminant:**

The truck leaked out approx. 3 bbls of clean crude oil, out the vent line. It contaminated about a 30' x40' area to a depth of about 3"-6"

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

There is minor immediate risk. Due to the clay liner and the on site berms.

**Areal Extent:**

**Potential Environmental Impacts:**

The clay liner on the pad site prevented any contamination and all the free oil was immediately vacuumed up, and the contaminated soil was disposed of at IHD.

**Action Taken or Planned:**

The Spill was reported at 4am to Dispatch. Dispatch then followed proper protocol and informed the Field Managers and our clean up team. Josiah who is the Williston Area Field Manager arrived onsite and assessed the situation and determined which clean up method we need to use. Which was over excavate the contaminated material and then replace with clean material. Any personnel that was not properly trained was asked to remove themselves from the location so we could do a proper clean up.

We called in a backhoe to do the excavation of the contaminated material and a side dump to haul it away to Indian Hills Disposal. We then removed the contaminated fill and replaced it with clean fill.

**Wastes Disposal Location:** Indian Hills Disposal.

**Agencies Involved:****Updates**

---

**Date:** 4/27/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release from a truck overflow, remained on location, according to the report. NDIC retains oversight.